

## **IECEx Quality Assessment Report Summary**

Page 1 of 2

Status: Issued

Date of issue: 2022-07-20

Valid until:2025-07-13

Audit date: 2022-07-13

## INTERNATIONAL ELECTROTECHNICAL COMMISSION **IEC Certification System for Explosive Atmospheres**

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: GB/BAS/QAR07.0023/10

QAR Free Ref. No.:

2242

Details of change: Re-assessment audit completed

Site(s) audited: Ion Science Limited

The Hive **Butts Lane** Fowlmere Royston SG8 7SL

**United Kingdom** 

Issuing ExCB:

**BAS - SGS Baseefa Limited** 

Manufacturer:

Ion Science Limited

The Hive **Butts Lane** Fowlmere Royston SG8 7SL

Location of Manufacturer: **United Kingdom** 

Product information: Gas detection and measurement equipment

Protection concept:

Ex i, d (Note: Concept d is included as a result of the use of a pre certified component. The Manufacturer has not been assessed for manufacture in relation to that concept.)

Related QARs:

GB/BAS/QAR07.0023/00 GB/BAS/QAR07.0023/03 GB/BAS/QAR07.0023/06 GB/BAS/QAR07.0023/09

GB/BAS/QAR07.0023/01 GB/BAS/QAR07.0023/04 GB/BAS/QAR07.0023/07

GB/BAS/QAR07.0023/02 GB/BAS/QAR07.0023/05 GB/BAS/QAR07.0023/08

Related Certificates (manual insertion)::

## **IECEx BAS 04.0033**

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx BAS 06.0057 issue: 2 IECEx BAS 06.0057X issue: 5 IECEx BAS 07.0030U issue: 1 IECEx BAS 07.0030U issue: 4 IECEx BAS 07.0030U issue: 7 IECEx BAS 07.0030U issue: 10 IECEx BAS 11.0014 issue: 0 IECEx BAS 11.0014 issue: 3 IECEx BAS 11.0014 issue: 6 IECEx BAS 11.0014 issue: 9 IECEx CML 20.0007 issue: 1 IECEx FTZU 16.0011X issue: 0 IECEx ITS 10.0036X issue: 1 IECEx ITS 10.0036X issue: 5 IECEx ITS 10.0036X issue: 8

IECEx BAS 06,0057 issue: 3 IECEx BAS 06.0065U issue: 2 IECEx BAS 07.0030U issue: 2 IECEx BAS 07.0030U issue: 5 IECEx BAS 07.0030U issue: 8 IECEx BAS 07.0030U issue: 11 IECEx BAS 11.0014 issue: 1 IECEx BAS 11.0014 issue: 4 IECEx BAS 11.0014 issue: 7 IECEx BAS 19.0049X issue: 0 IECEx FTZU 14.0030X issue: 0 IECEx FTZU 16.0011X issue: 1 IECEx ITS 10.0036X issue: 3

IECEx ITS 10.0036X issue: 6

IECEx ITS 10.0036X issue: 9

IECEx BAS 06.0057X issue: 4 IECEx BAS 07.0030U issue: 0 IECEx BAS 07.0030U issue: 3 IECEx BAS 07.0030U issue: 6 IECEx BAS 07.0030U issue: 9 IECEx BAS 07.0030U issue: 12 IECEx BAS 11.0014 issue: 2 IECEx BAS 11.0014 issue: 5 IECEx BAS 11.0014 issue: 8 IECEx CML 20.0007 issue: 0 IECEx FTZU 14.0030X issue: 1 IECEx ITS 10.0036X issue: 0 IECEx ITS 10.0036X issue: 4

IECEx ITS 10.0036X issue: 7



## IECEx Quality Assessment Report Summary

| ТМ            | Assessment Report Summary                |             |
|---------------|--|-------------|
| QAR Ref. No.: | GB/BAS/QAR07.0023/10                     | Page 2 of 2 |
| Comments:     | See BAS/QAR 06.0035 for previous details |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |
|               |  |             |